



JANEX INC.

Exclusive Independent Exporter for
Continental Commercial Products LLC

WHAT FLOOR PAD TO RECOMMEND

These are good starting recommendations. Because of the vast differences in finishes, machines and operator techniques, results may vary.

APPLICATION	R.P.M. OF MACHINE	PAD RECOMMENDATIONS	WET OR DRY CHEMICAL	RESULTS
STRIPPING	175 - 350	1. Black Strip	Strip Solution Wet	For Removal of All Finish, Wax Buildup and Dirt Down to the Original Surface.
		2. Brown Strip		
		3. Dark Blue, Hi-Pro		
		4. Black Xtra		
SCRUBBING	175 - 350	1. Green Scrub	Cleaner Wet	For Thoroughly Cleaning All Dirt And Some Finishes From Heavily Soiled Floors.
		2. Blue Scrub		
SPRAY BUFFING	175 - 350	1. Regular Red Spray Buff	Spray Buff Solution Wet	Spray Buff Solution Will Clean When and Shine When Dry. Sometimes Called "Restoring the Finish."
	350 - 1200	2. Aqua Hi Speed Spray Buff		
	1200+	3. RPM Ultra Ivory		
BUFFING	175 - 350	1. White Polish (For High Gloss)	Dry or Light Water Mist	For Polishing a Clean Dry Floor. Upgrading the Finish Quality After Scrubbing or Spray Buffing.
	350 - 1200	2. Aqua Hi Speed		
BURNISHING	Propane Machines (1500 - 3000)	1. RPM Ultra Ivory	Dry	For Applying Heat and Friction Using Ultra High Speed Machines to Produce a "High" Shine and Harden the Finish. "Levels" the Finish.
		2. Natural Gray		
	Electric + Battery Machines (1500 - 3000)	1. Natural Lite	Dry	
		2. Aqua Hi Speed Spray Buff		
	3. Natural Gray			
	4. UHS Blue			

Janex Inc.
30 High Street
Norwalk, CT 06851
(203) 838-9608 Fax: (203)854-0588
janex@snet.net

